## Installation Instructions for 2102141

- Copy NK.bin to temporary folder under PCCUNGC folder.
- Using PCCUNGC's TFLoader, browse the operating system entry to NK.bin.
- Connect to NGC.
- Start download.